DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-023415 Address: 333 Burma Road **Date Inspected:** 07-May-2011

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes No Li yan hua **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Weld Procedures Followed:** N/A **Electrode to specification:** No Yes No Yes N/A N/A **Qualified Welders:** No **Verified Joint Fit-up:** Yes No N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component: OBG** Components

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, S.Chandrakumar was present during the times noted above for observations relative to the work being performed. **BAY#19**

FCAW welding of weld is identified as 2F-094 of SA6031-001for SA6031. The welder is identified as 062807. ZPMC QC is identified as Mr. Li ping. The welding variables recorded by QC are appeared to comply with the WPS-B-T-2132-ESAB.

FCAW welding of weld is identified as 2F-058 of SA6529-001 for SA6529. The welder is identified as 062749. ZPMC QC is identified as Mr. Li ping. The welding variables recorded by QC are appeared to comply with the WPS-B-T-2132-ESAB.

FCAW welding of weld is identified as 3F-093 of SA6530-001 for SA6530. The welder is identified as 062739. ZPMC QC is identified as Mr. Li ping. The welding variables recorded by QC are appeared to comply with the WPS-B-T-2133-ESAB.

FCAW welding of weld is identified as 2F-130/131 of SA6531-001 for SA6531. The welder is identified as 062739. ZPMC QC is identified as Mr. Li ping. The welding variables recorded by QC are appeared to comply with the WPS-B-T-2132-ESAB.

FCAW welding of weld is identified as 3F-055/056 of SA6029-003 for SA6029. The welder is identified as

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

062749. ZPMC QC is identified as Mr. Li ping. The welding variables recorded by QC are appeared to comply with the WPS-B-T-2133-ESAB.

FCAW welding of weld is identified as 3F-056 of SA6030-006 for SA6030. The welder is identified as 062807. ZPMC QC is identified as Mr. Li ping. The welding variables recorded by QC are appeared to comply with the WPS-B-T-2133-ESAB.

FCAW welding of weld is identified as 3G-047 of SA6531-001 for SA6531-001. The welder is identified as 062807. ZPMC QC is identified as Mr. Li ping. The welding variables recorded by QC are appeared to comply with the WPS-B-T-2233-ESAB.

ZPMC personnel performing Heat straightening of bike path side plate (BKPK65A) is in progress as per Approved HSR1 (B)-10532.

This QA inspector performed MT 15% of weld areas previously tested and accepted by ZPMC Quality Control personnel. This QA inspector generated an MT report for this date. The members are identified as OBG Suspender bracket and bike path. The weld designations reviewed as follows.

BK25A5-001-015,018,027,029,030,039,041,051,053,054

BK25A7-001-131,141,155,160,174,192

BK25A7-001-151,165,166,179,180,188,121,123

BK25A8-001-052,053,065,064,061,062,069,073,075,049

BK25A6-001-006,007,011,015,016,060,061,019,049,053,032

SB022-106-004

This QA inspector performed UT 10% of weld areas previously tested and accepted by ZPMC Quality Control personnel. This QA inspector generated an UT report for this date. The members are identified as OBG Suspender bracket. The weld designations reviewed as follows.

SB022-106-004.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant Conversation.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang-15--0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Kumar,Chadra	Quality Assurance Inspector
Reviewed By:	Patel, Hiranch	QA Reviewer